## PR001 27-Jun-11

## **Preliminary Report of Accident**

## U.S. Department of Labor

Mine Safety and Health Administration

"//

1. Accident Type:	2. Accident	3. Date/Time of Accident 4. Date/T			4. Date/Time of De	ath	5, Fatal Case No				
Fatal Injury	Fall of Face, Rib, Pillar or Highwall				06/27/2011 01:50 AM 06/			06/27/2011	01:50 AM	8	
6. Mine Information :				······································							
a) Mining Company Name			b) Mine Name				c)	Parent of Mining (	Company		
Rhino Eastern LLC	no Eastern LLC Eagle #1					Rhino Resource Partners LP					
7. Mine Location :	Mine Location : a) City b) County					c) State 8. Mine I			D Number: 9. Union:		
Bolt			Raleigh	WV			46-08758		NO		
10. Primary Mineral Mined:			1. Number of	) Underground c) Open Pit/Q			Quarry d) Mill/Prep Plant		e) Other		
BITUMINOUS		IVE	ne Employees:	95	88				<b>,</b>	7	
12. Contractor Name:							13. Unio	)n	14. Centrae	ctor ID Number:	
15, Contractor Address:	a)	City		b)	County	•		c) State	d) Z	ip Code	
16. Number of Contractor E	nployees:	a) Tota	ıl b)	Underground	с) Орс	n Pit/Qu	iarry	d) Mill/Pr	ep Plant	c) Other	
					T						
17. Number of Persons in Mi					18. Number			ounted For:			
a) Mine Employees:	18	b) Cont	ractor Employe	:5:	a) Mine E	mployee	S:	b) Co	ontractor Emp	<del></del>	
19) Location of Accident  X 01-Underground		03-Орег	ı Pit	X 07-Advance	Mining	30-N	Aill/Prep	Plant Oth	er (specify)	20, Mining Height:	
02-Surface at Undergro	nad	= :	lge Mining	08-Retreat		_	Office Fac	_	(,)	Feet Inches 9 7	
21. Nonfatal Injuries:		22. Fatal Inju									
24. Noncatar injuries.	0	<i>22.</i> 1 atas 111 <sub>1</sub> u	1								
23. Victim Information:		a) Nam Joseph Cas			b) Age 33						
c) Regular Job Title:		. осор. г		y at Time of Accie					X N	Ine Employee	
Crew Leader					Cleaning r	ib to in:	stall sup	port	( <u>FC</u> ) *-		
24. Experience : Years W	eeks Days		Years We	eks Days		Ye	ars Weeks	Days		Years Weeks Days	
a) Total:	16 2	b) at the n	nine: 1 16	6 2 c) at	activity (23d)		0 10	2 d) with	Contractor		
25. Autopsy Performed:	If Yes, L	ocation						26. Mine Telepho	ne No.:		
YES Charleston	. WV							(304	) 682-0644		
								onerations			
27. Description of Accident (		oment involve	d, the exact locat	ion in the mine, a	ind status of res	cue and	recovery	operations,.			
27. Description of Accident ( On June 27, 2011, at applied the process of cleaning to thick, by 37" tall. The accident the process of cleaning to the process of the proces	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equip proximately the mine flo	1:50 a.m., or to install t	Joseph Casse imbers when t	ll, crew leader, he brow fell fro	received fata m the top of t	l crushi he rib.	ng injurio The bro	es from a coal ar w measured app	roximately 1	00" long, by 32"	
On June 27, 2011, at application the process of cleaning t	include equiporoximately he mine flo cident occu	1:50 a.m., vor to install t rred just out	Joseph Casse imbers when t by the active s	il, crew leader, he brow fell froi section. An acc	received fata m the top of t sident investig	I crushi he rib. gation v	ng injurid The bro vas imm	es from a coal ar w measured app ediately initiated	roximately 1 and is ongo	00" long, by 32" ing at this time.	
On June 27, 2011, at applied the process of cleaning to thick, by 37" tall. The accordance of the control of th	include equiporoximately ne mine flo cident occu	1:50 a.m., vor to install t rred just out	Joseph Casse imbers when t by the active s	il, crew leader, he brow fell froi section. An acc	received fata m the top of t sident investig	I crushi he rib. gation w	ng injurid The bro vas imm	es from a coal ar w measured app ediately initiated	roximately 1 and is ongo	00" long, by 32" ing at this time.	
On June 27, 2011, at app the process of cleaning to thick, by 37" tall. The accordance of the accordan	include equiporoximately ne mine flo cident occu	1:50 a.m., vor to install t rred just out	Joseph Casse imbers when t by the active s	il, crew leader, he brow fell from section. An acc	received fata m the top of t cident investig	I crushi he rib. gation w	ng injurid The brovas immo	es from a coal ar w measured app ediately initiated	roximately 1 and is ongo	00" long, by 32" ing at this time.	
On June 27, 2011, at app the process of cleaning to thick, by 37" tall. The accordance of the accordan	this notice is cident.	1:50 a.m., vor to install t rred just out	Joseph Casse imbers when t by the active s	II, crew leader, he brow fell from section. An acc	received fata m the top of t cident investig t represent fina	I crushi he rib. gation w	ng injurid The brovas immo	es from a coal ar w measured appediately initiated egarding the nature 33. Eve	roximately 1 and is ongo e of the incider	00" long, by 32" ing at this time.	
The information provided in regarding the cause of the ac 28. Equipment Manufacture 30. District:	this notice is cident.	1:50 a.m., vor to install t rred just out	Joseph Casse imbers when t by the active s	II, crew leader, he brow fell from section. An accordance of the brow fell from section. An accordance of the brown fice:  Mt. Hop  35. MSHA Per	received fata m the top of t cident investig t represent fina	l crushi he rib. gation w I determ 29. N	ng injurid The brovas immo	es from a coal ar w measured appediately initiated egarding the nature 33. Eve	roximately 1 and is ongo e of the incident the thicker of the incident of the	00" long, by 32" ing at this time.  nt or conclusions	
The information provided in regarding the cause of the ac 28. Equipment Manufacture C0400 Mt.	this notice is cident.	1:50 a.m., or to install to rred just out	Joseph Casse imbers when to by the active so liminary data Off.	II, crew leader, he brow fell from section. An accordance of the brow fell from section. An accordance of the brown fice:  Mt. Hop  35. MSHA Per	received fata m the top of t cident investig t represent fina e WV son Notified:	l crushi he rib. gation w I determ 29. N	ng injurid The brovas immo	es from a coal ar w measured appediately initiated egarding the nature 33. Eve	roximately 1 and is ongo e of the incident the thicker of the incident of the	00" long, by 32" ing at this time.  nt or conclusions  7995  Time  02:04 A	
The information provided in regarding the cause of the acceptance of the cause of the acceptance of th	this notice is cident.	1:50 a.m., or to install to rred just out	Joseph Casse imbers when to by the active so liminary data Off.	II, crew leader, he brow fell from the brow fell from the brow fell from the brown fell from the brown fell from the brown feet.  NLY and does not be brown feet.  Mt. Hop Charles	received fata m the top of t cident investig t represent fina e WV son Notified:	l crushi he rib. gation w I determ 29. N	ng injurid The brovas immo	es from a coal ar w measured appediately initiated egarding the nature 33. Eve	roximately 1 and is ongo e of the incide ent Number: 6287 ate /2011	00" long, by 32" ing at this time.  nt or conclusions  7996  Time 02:04 A	